

# ID 1000-KIT

## Three Point Light Kit QUICKSTART GUIDE



### What's included

- 3 x ID 1000 Light
- 3 x Light Stand
- 3 x AC Adapter + Power Cord
- 3 x Remote Control
- Light Carrying Bag
- Light Stand Carrying Bag

Checked by

### CONDITIONS OF WARRANTY SERVICE

- Free service for one year from the day of purchase if the problem is caused by manufacturing errors.
- The components and maintenance service fee will be charged if the warranty period has expired.

Free Service will not be Provided in the Following Situations: (\* Even if the product is still within the warranty period.)


- Damage caused by abuse or misuse, dismantling, or changes to the product not made by the company.
- Damage caused by natural disaster, abnormal voltage, and environmental factors etc.

# ID 1000-KIT

## Three Point Light Kit QUICKSTART GUIDE

### GETTING STARTED

1. Connect the included AC Adapter to power the ID 1000 light.
2. Turn the light on / off with the Power Switch.
3. Control the amount of the light with the Dimmer knob. Adjust the intensity of the light by turning the Dimmer Knob clock-wise to increase the intensity and counter clock-wise to reduce it.
4. The ID 1000 can also be powered by pro battery (optional accessories).



### Put it Where You Want It

The ID 1000 comes with a movable and detachable Light Stand Adapter allowing you to mount your light either horizontally or vertically.

# ID 1000-KIT

## Three Point Light Kit QUICKSTART GUIDE



### Remote Control Buttons

#### A. Power On/Off

Press and hold for 5 seconds to sync remote control to light.

#### B. Press button to adjust 4 levels of light intensity.

Press and hold for 5 seconds to enable/disable sound.

#### C. Hold down to increase light intensity

#### D. Hold down to decrease light intensity

### • Pro Battery Option



### Optional Accessories

- V17PBK-S Pro Battery Kit \$149.00
- V17PBK-A Pro Battery Kit \$149.00
- IB-L130A AB Mount Professional Battery \$375.00
- IB-L130S V Mount Professional Battery \$375.00